


PORTAPEDANE

MATERIALE DI COSTRUZIONE lega di alluminio 2024, acc. Inox AISI 303
LAVORAZIONI fresatura e tornitura CNC
TRATTAMENTI SUPERFICIALI ossidazione anodica colore



- 1.
- 2.
- 3.

assemblare i portapedane sul telaio come mostrato in figura utilizzando la bussola e le viti fornite;

ATTENZIONE!! NOTA BENE!!


Si possono utilizzare con pedane standard o di altri produttori. Tuttavia si consiglia l'uso dei portapedane abbinati a pedane CSP per scongiurare rotture o malfunzionamenti. L'azienda produttrice non risponde per danni causati dall'utilizzo di altre pedane non prodotte da CSP.

Produttore:
O.M. Costa Snc
fraz. Cervarolo
I3019 Varallo Sesia
(Vercelli) Italia
100% PRODOTTO ITALIANO

Tutte le parti speciali CSP devono essere applicate esclusivamente a motocicli non destinati a circolare su strada, ma solo nell'ambito di competizioni e appositi campi gara. L'assemblaggio deve essere eseguito da tecnici e/o professionisti del settore. L'azienda produttrice non risponde dei danni causati dall'incorretto utilizzo dei propri prodotti.

PORTAPEDANE

MATERIALE DI COSTRUZIONE lega di alluminio 2024, acc. Inox AISI 303
LAVORAZIONI fresatura e tornitura CNC
TRATTAMENTI SUPERFICIALI ossidazione anodica colore



- 1.
- 2.
- 3.

assemblare i portapedane sul telaio come mostrato in figura utilizzando la bussola e le viti fornite;

ATTENZIONE!! NOTA BENE!!


Si possono utilizzare con pedane standard o di altri produttori. Tuttavia si consiglia l'uso dei portapedane abbinati a pedane CSP per scongiurare rotture o malfunzionamenti. L'azienda produttrice non risponde per danni causati dall'utilizzo di altre pedane non prodotte da CSP.

Produttore:
O.M. Costa Snc
fraz. Cervarolo
I3019 Varallo Sesia
(Vercelli) Italia
100% PRODOTTO ITALIANO

Tutte le parti speciali CSP devono essere applicate esclusivamente a motocicli non destinati a circolare su strada, ma solo nell'ambito di competizioni e appositi campi gara. L'assemblaggio deve essere eseguito da tecnici e/o professionisti del settore. L'azienda produttrice non risponde dei danni causati dall'incorretto utilizzo dei propri prodotti.

FOOTPEGS HOLDERS

CONSTRUCTION MATERIAL alu alloy 2024, stainless steel 303
MACHINING CNC turning and milling
SURFACE TREATMENT coloured anodic oxidation



1. 2. 3. assemble on the footrest on the frame as shown in figure using the bushing and the screws provided;


CAUTION!!! LOOK!!

They can be used with standard footrests or those from other manufacturers. However, we recommend using the footrest holders in conjunction with CSP footrests to avoid breakage or malfunction.
The manufacturer is not liable for damage caused by the use of footrests other than those manufactured by CSP.

Manufacturer:
O.M. Costa Snc
fraz. Cervarolo
I3019 Varallo Sesia
(Vercelli) Italia
100% PRODOTTO ITALIANO
All CSP's special parts must only be applied to motorcycles non intended for road use, but only in competitions track and race fields.
The assembly must be performed by technicians or professionals.
Manufacturer is not liable for damage caused by the incorrect use of its products.

FOOTPEGS HOLDERS

CONSTRUCTION MATERIAL alu alloy 2024, stainless steel 303
MACHINING CNC turning and milling
SURFACE TREATMENT coloured anodic oxidation



1. 2. 3. assemble on the footrest on the frame as shown in figure using the bushing and the screws provided;

CAUTION!!! LOOK!!

They can be used with standard footrests or those from other manufacturers. However, we recommend using the footrest holders in conjunction with CSP footrests to avoid breakage or malfunction.
The manufacturer is not liable for damage caused by the use of footrests other than those manufactured by CSP.

Manufacturer:
O.M. Costa Snc
fraz. Cervarolo
I3019 Varallo Sesia
(Vercelli) Italia
100% PRODOTTO ITALIANO
All CSP's special parts must only be applied to motorcycles non intended for road use, but only in competitions track and race fields.
The assembly must be performed by technicians or professionals.
Manufacturer is not liable for damage caused by the incorrect use of its products.